

Dodson International Lycoming Engines For Sale, 6-3-2010 phone: 1.785.878.4000, fax: 1.785.878.4444,
sales@dodson.com

Model	Serial #	TSN	TSO	Cond	PS	Dial	Notes:
O-320-D1D	RL-19384-39A	SFOH	417	AR	Yes	.001	
O-320-D1D	RL-18629-39A	2537	537	AR	Yes	.001	
IO-320-B1A	L-3602-55A	7034.4	277.4	AR	Yes	.006	
IO-320-B1A	L-3078-55A	6006.66	277.4	AR	Yes	.006	
IO-320-B1A	RL-2557-55A	353.3	N/A	AR	YES	.003	
IO-320-B1A	RL-5863-55A	353.3	N/A	AR	YES	.010	
IO-320-B1A	L-392-55	4045.4	430.3	AR	Yes	.007	
HIO-360-E1AD	L-21141-51A	4653.5	907.5	AR	Yes		
LIO-360-C1E6	L-585-67A	UNKN	30.41	AR	No		Field O/H
O-435-C	L-00192-8	*3124.9	*432.9	RP	No		Fire Damaged Log-Estimated Time
O-540-F1B5	L-26157-40A	1338.2	N/A	AR	YES		
O-540-J3C5D	L-21437-40E	5649.74	371.3	AR	YES		
TIO-540-C1A	L-3477-61	1313.29	77.79	AR	Yes	.003	MRS-Intake broken off-rust & corrosion
TIO-541-E1A4	L-1467-59C	UNKN	UNKN	AR	Yes	.002	Intake tubes rusted- No Logbooks
TIO-541-E1A4	L664-59	UNKN	UNKN	AR	No	.002	No Logbooks
TIO-541-E1B4	RL-607-59	4232.2	1632.8	AR	Yes	.002	
TIO-541-E1C4	RL-388-59C	3202.85	1089.2	AR	Yes	.003	